

HORNADY STUCK CASE REMOVER INSTRUCTIONS

The Hornady Stuck Case Remover is designed to remove stuck cases from the size die body.

1. Back deprime spindle out as far as it will go.
2. Remove die from press.
3. Drill hole in primer pocket with #7 drill provided.
4. Tap the hole with ¼" x 20 Tap provided.
5. Place the Stuck Case Remover Body over the end of the Die; cupped sided facing the bottom of the Die.
6. Place the washer on the Socket Head Cap Screw (SHCS) and insert the Screw thru the Case Stuck Remover Body, and screw it into the threaded case. Tighten down the Socket Head Cap Screw against the Body. This will pull the case out of the Die.

PARTS LIST:


390128 - Washer

392067 - #7 Drill

398388 - ¼"x20x1½" SHCS

392066 - ¼"x20 Tap

392068 - Body



Hornady[®]
Accurate. Deadly. Dependable.

3625 Old Potash Hwy • P.O. Box 1848 • Grand Island, NE 68802

308-382-1390 • www.hornady.com